

PROJECT RECORDS

Tethys-Plantgeria Ltd has outstanding project records that spans over two decades (1990 – Date). The lists of all projects in progress and those completed are provided below.

ONGOING CONTRACTS

CLIENT: **ZYTE INTEGRATED LTD**
LOCATION/PROJECT: Agbara field
DESCRIPTION OF WORK: Hire and Operation of Security Patrol Boat (Conqueror Due) for Security Activities
COMMENCEMENT DATE: July, 2021

CLIENT: **SPDC**
MAIN CONTRACTOR: HYPROPS
LOCATION/PROJECT: Forcados & Bonny Field
DESCRIPTION OF WORK: Provision of Diving and Marine Maintenance Services at SPDC offshore Bonny and Forcados field
COMMENCEMENT DATE: December, 2020

CLIENT: **NAOC**
LOCATION/PROJECT: Brass Terminal
DESCRIPTION OF WORK: Patrol Services (Conqueror Due) at Brass Terminal
COMMENCEMENT DATE: August 30, 2017

CLIENT: **NAOC**
CONTRACT DESCRIPTION: Provision of Diving & Offshore Maintenance Services and Supply of Diving Support Vessel (DSV Liberty) for NAOC operation areas/Brass Oil Field
COMMENCEMENT DATE: January 31, 2005

PROJECTS COMPLETED WITHIN THE LAST 5 YEARS

YEAR: **2021**
CLIENT: AUGUSTA MARITIME SERVICES
LOCATION/PROJECT: Mellitah Terminal, Libya
DESCRIPTION OF WORK: Provision of Diving Maintenance/Services at Western Libya Mellitah Terminal (ENIGAS)

YEAR: **2020**
CLIENT: DAEWOO ENGINEERING & CONSTRUCTION NIG. LTD
LOCATION/PROJECT: NLNG Bonny Field
DESCRIPTION OF WORK: Demolition of MOF2 General Cargo Berth Project

YEAR: **2020**
CLIENT: GLOBAL SPECTRUM ENERGY SERVICES LTD / ADDAX
LOCATION/PROJECT: Okwori Field
DESCRIPTION OF WORK: Hire and Operation of Security Patrol Boat (Conqueror Tre) for Security Activities

YEAR:	2019
CLIENT:	SPDC
MAIN CONTRACTOR:	HNL
LOCATION/PROJECT:	Forcados & Bonny Field
DESCRIPTION OF WORK:	Call Off Emergency works at Forcados and Bonny Fields
YEAR:	2019
CLIENT:	NAE
LOCATION/PROJECT:	Okwori Field
DESCRIPTION OF WORK:	Hire and Operation of Security Patrol Boat (Conqueror Tre) for Security Activities
YEAR:	2019
CLIENT:	SPDC
LOCATION/PROJECT:	Ogbotobo Flow Station
DESCRIPTION OF WORK:	Ogbotobo Concrete Barge Scour Rectification Project
YEAR:	2019
CLIENT:	PISCES OFFSHORE
LOCATION/PROJECT:	Asasa Field
DESCRIPTION OF WORK:	Provision of Inspection Class ROV Spread and Personnel for Asasa VA and Asasa VB Platform Jacket Face Survey at MPN Field
YEAR:	2019
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Oil Field
DESCRIPTION OF WORK:	Complete Inspections and Reporting of Single Point Mooring System 1 & System 2 and BOP.
YEAR:	2019
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Oil field
DESCRIPTION OF WORK:	Subsea Marine Hoses Change out on SPM1 at Brass Oil field
YEAR:	2019
CLIENT:	NigerDive Ltd
LOCATION/PROJECT:	Agbara field
DESCRIPTION OF WORK:	Underwater Inspection of Sealines and Structural Jacket at Agbara field
YEAR:	2019
CLIENT:	SPDC
LOCATION/PROJECT:	SPDC EA Field
DESCRIPTION OF WORK:	Accommodation and Security Coverage at SPDC EA field
YEAR:	2018
CLIENT:	Ripen Marine Contractors (RMC)
LOCATION/PROJECT:	OML 119 Okono field
DESCRIPTION OF WORK:	Provision of ROV and Personnel for Leakage intervention at OML 119 Okono field FPSO Mystras

YEAR:	2018
CLIENT:	SPDC
LOCATION/PROJECT:	Ogunu Jetty
DESCRIPTION OF WORK:	Underwater inspection of SPDC Ogunu Jetty
YEAR:	2018
CLIENT:	PISCES/MPN
LOCATION/PROJECT:	MPN Asabo Field
DESCRIPTION OF WORK:	ROV Underwater Survey of Asabo platform jacket face and flare stack at Mobil field
YEAR:	2018
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Offshore
DESCRIPTION OF WORK:	BOP Riser Leakage Repairs
YEAR:	2018
CLIENT:	SPDC
LOCATION/PROJECT:	Ogbotobo Flow Station
DESCRIPTION OF WORK:	Underwater Survey of Concrete Barge, Well Heads and Sheet piles at Ogbotobo flow station
YEAR:	2018
CLIENT:	SPDC
LOCATION/PROJECT:	SPDC Bonny and Forcados
DESCRIPTION OF WORK:	Provision of Diving Services at SPDC Oil Field - (SSH & FH Change out Campaign at BSPM 1, 2 & 3)
YEAR:	2018
CLIENT:	SPDC
LOCATION:	Forcados field
DESCRIPTION OF WORK:	Provision of DSV, Equipment & Personnel for Oil Leak Intervention at Forcados SPM 1 & 2
YEAR:	2017
CLIENT:	AAXAL / NPDC
LOCATION:	OML 119 Okono field
DESCRIPTION OF WORK:	Provision of DSV, Equipment & Personnel for Structural integrity inspection of FPSO Mystras
YEAR:	2017
CLIENT:	SPDC
LOCATION:	Forcados field
DESCRIPTION OF WORK:	Underwater Survey of CLP Platform at Forcados Oil field
YEAR:	2017
CLIENT:	SPDC
LOCATION/PROJECT:	SPDC EA Field
DESCRIPTION OF WORK:	Provision of DSV and equipment for In-water survey of offshore facilities at EA field

YEAR: 2017
CLIENT: SPDC
LOCATION: SPDC Oil Fields (Forcados and Bonny Oil Fields)
CONTRACT DESCRIPTION: Provision of Diving services and Diving Support Vessel (DSV Melody) at SPDC Oil Fields

YEAR: 2016
CLIENT: NAOC
LOCATION: Brass Oil Field
CONTRACT DESCRIPTION: 36" Sealines Inspection at Brass Oil Field.

YEAR: 2016
CLIENT: NAOC
LOCATION/PROJECT: BRASS OIL FIELD
DESCRIPTION OF WORK: Underwater Structural Survey for BOP at Brass Oil Field.

YEAR: 2016
CLIENT: NAOC
LOCATION/PROJECT: BRASS OIL
DESCRIPTION OF WORK: Provision of Security Boat and Naval Rating for BOP project at Brass Oil Field.

YEAR: 2016
CLIENT: NAOC
LOCATION/PROJECT: BRASS OIL FIELD
DESCRIPTION OF WORK: Provision of Security Boat and Naval Rating for 36" Sealine Inspection project at Brass Oil Field.

OTHER COMPLETED PROJECTS

YEAR: 2014
CLIENT: NAOC
LOCATION: Agwe-titi (Delta state)
CONTRACT DESCRIPTION: 24" Gas Pipeline Stabilization at Agwe-titi (Delta state) - PHASE 2

YEAR: 2014
CLIENT: NAOC
LOCATION/PROJECT: AGWE TITI
DESCRIPTION OF WORK: Hire and Operation of Security Patrol Boats (Conqueror Uno) for Security Activities in OB-OB/Agwetiti Pipeline Stabilization Project

YEAR: 2013
CLIENT: NAOC
CONTRACT DESCRIPTION: 24" Gas Pipeline Stabilization at Agwe-titi (Delta state) - PHASE 1
LOCATION: Agwe-titi (Delta state)

YEAR: 2012
CLIENT: EXXON MOBIL
LOCATION/PROJECT: MOBIL FIELD (IDOHO)
DESCRIPTION OF WORK: Hire and Operation of Security Patrol Boats (Conqueror Due) for Security Activities in Exxon Mobil Operations

YEAR:	2012
CLIENT:	EXXON MOBIL
LOCATION/PROJECT:	MOBIL FIELD (IDOHO)
DESCRIPTION OF WORK:	Hire and Operation of Security Patrol Boats (Conqueror Uno) for Security Activities in Exxon Mobil Operations
YEAR:	2012
CLIENT:	CELTIC AFRICA LTD (CELTIC)
LOCATION/PROJECT:	Nigeria
DESCRIPTION OF WORK:	Hire of AHTS DP 1 Melody
YEAR:	2012
CLIENT:	AFREN ENERGY RESOURCES LIMITED
LOCATION/PROJECT:	
DESCRIPTION OF WORK:	Provision of one (1) Anchor Handling Tug Supply Vessel
YEAR:	2012
CLIENT:	SPDC
LOCATION/PROJECT:	FORCADOS TERMINAL
DESCRIPTION OF WORK:	Forcados Spm 2 Subsea Hose String Inspection/Replacement and Sealine Pipe Inspection
YEAR:	2010 – 2012
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Oil Field & Swamp Area Operation
DESCRIPTION OF WORK:	Provision of Security Boat "Conqueror One" with Naval Personnel on Board
YEAR:	2011 – 2012
CLIENT:	SHELL PETROLEUM DEVELOPMENT CO. OF NIGERIA
LOCATION/PROJECT:	Bonny Terminal SPM2
CONTRACT DESCRIPTION:	Floating/Subsea Hoses Change-out on CALM Buoy System
YEAR:	2011
CLIENT:	AENR
LOCATION/PROJECT:	OML 116 – Agbara Oil Field
DESCRIPTION OF WORK:	Recertification of Platforms: Special Survey and Remedial Intervention (NDT) – Air & Saturation Diving
YEAR:	2010 - 2011
CLIENT:	AENR
LOCATION/PROJECT:	OML 116 – Agbara Oil Field
DESCRIPTION OF WORK:	Retrofit/Replacement of No. 456 Sacrificial anodes on Agbara Platforms and Installation of 2 units of CP Monitoring System (Air and Saturation Diving Operations)
YEAR:	2010
CLIENT:	NPDC/AENR
LOCATION/PROJECT:	OML 119 – Okono Oil Field
DESCRIPTION OF WORK:	Okono/Okpoho 16" Pipeline, 1 st , 2 nd & 3 rd Leakage repairs (Extra Work – Diving Saturation System)

YEAR:	2010
CLIENT:	NAOC
LOCATION/PROJECT:	Beniboye Oil Field
DESCRIPTION OF WORK:	Emergency Diving Service at Beniboye Clusters 1 and 2
YEAR:	2009
CLIENT:	AENR
LOCATION/PROJECT:	OML 119, Okono/Okpoho Field
DESCRIPTION OF WORK:	Supply of CALM Buoy Spare Parts & Mooring System for Okono Terminal
YEAR:	2008
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Terminal
DESCRIPTION OF WORK:	Inspection and Repair of SBM 1 ENIF at Brass
YEAR:	2008
CLIENT:	AENR
LOCATION/PROJECT:	Agbara Oil Field
DESCRIPTION OF WORK:	Supply of Mooring Buoy System
YEAR:	2008
CLIENT:	AENR
LOCATION/PROJECT:	Agbara Oil Field
DESCRIPTION OF WORK:	Supply and Construction of Buoy Mooring System
YEAR:	2007
CLIENT:	MOBIL PRODUCING NIG. UNLTD/PROJECT MASTER
LOCATION/PROJECT:	Various Offshore Locations
DESCRIPTION OF WORK:	Offshore Construction/Installation Services Contract (Main Diving activities include: Anode Installation on Platform Jackets, Riser Repair/Installation and General Visual Inspection)
YEAR:	2007
CLIENT:	AENR/NPDC
LOCATION/PROJECT:	Brass Oil Field
DESCRIPTION OF WORK:	Hire and Operation of 1 No. Supply Vessel (MV Liberty) for Okono/Okpoho Field Operation
YEAR:	2007
CLIENT:	NPDC LTD, NIGERIA
CONTRACT DESCRIPTION:	Hire and Operation of 1 No. Supply Vessel (MV Liberty) for Okono/Okpoho Field Operation
LOCATION:	Okono/Okpoho Field (OML 119)
YEAR:	2007
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Terminal
DESCRIPTION OF WORK:	Supply of Submarine Hoses
YEAR:	2007
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Terminal
DESCRIPTION OF WORK:	Provision of an SPM CALM Buoy Navigational Aid

YEAR: 2006
CLIENT: NPDC/AENR
LOCATION/PROJECT: OML 119, Okono/Okpoho Field
DESCRIPTION OF WORK: Underwater Inspection of the CALM Buoy & Offloading System

YEAR: 2006
CLIENT: NAOC
LOCATION/PROJECT: Brass Terminal
DESCRIPTION OF WORK: Dredging of fire-fighting water basin

YEAR: 2006
CLIENT: NAOC
LOCATION/PROJECT: Nembe Creek, Bayelsa State (NIGERIA)
DESCRIPTION OF WORK: Diving Intervention for the 24" Ogodu-Brass Pipeline Spillage

YEAR: 2006
CLIENT: SAIPEM
LOCATION/PROJECT: Bonny Island, (NIGERIA)
DESCRIPTION OF WORK: Cable Fibre Optic Recovery

YEAR: 2005
CLIENT: AUGUSTA MARITIME SERVICES
LOCATION/PROJECT: Libya
DESCRIPTION OF WORK: Provision of Offshore Diving Maintenance Services at Western Libya Mellitah Terminal

YEAR: 2005
CLIENT: AGIP ENERGY
LOCATION/PROJECT: Okono Field, (NIGERIA)
DESCRIPTION OF WORK: Top Side and Diving Survey on SBM Calm Buoy

YEAR: 2005
CLIENT: SAIPEM
LOCATION/PROJECT: Bonny Island, (NIGERIA)
DESCRIPTION OF WORK: Provision of Diving Service for NAOC Bonny Island 36" Gas Pipeline

YEAR: 2005
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Field, (NIGERIA)
DESCRIPTION OF WORK: ENIF SPM Calm Buoy Inspection and Relocating

YEAR: 2004 – DATE
CLIENT: NAOC Port Harcourt (NIGERIA)
DESCRIPTION OF WORK: Diving services and Offshore Maintenance at Brass Oil Terminal and Agbara Oil Field.
Drilling Platform, Production Platform, Gas Flare
Buoy Operating Platform
No 2 SPM
No 2 x 32" Pipeline
No 1 x 36" Export Pipeline
AGBARA OIL FIELD No 1 x 12" Pipeline
No 1 x 17" Gas Flow Line
(Contract won for the first time in 1991)

YEAR:	2003
CLIENT:	NAOC
LOCATION/PROJECT:	Orashi River, (NIGERIA)
DESCRIPTION OF WORK:	Pipeline Repair and Diving Assistance for laying of new 14" pipeline.
YEAR:	2003
CLIENT:	NAOC
LOCATION/PROJECT:	Brass Oil Terminal, (NIGERIA)
DESCRIPTION OF WORK:	Revamping of Underwater Structures of Buoy Operating Platform. (40 Anodes installation, jacket cleaning, splash zone coating, Bottom debris) – Saturation System
YEAR:	2002
CLIENT:	NAOC / AENR
LOCATION/PROJECT:	OML – 119 Okono Field, (NIGERIA)
DESCRIPTION OF WORK:	Diving Service for Christmas Tree Installation at Okono 4 & 5 Well Heads (Saturation System)
YEAR:	2002
CLIENT:	NAOC
LOCATION/PROJECT:	OML – 119 Okono Field, (NIGERIA)
DESCRIPTION OF WORK:	Diving Service for Christmas Tree Installation at Okono 2 & 3 Well Heads (Saturation System)
YEAR:	2002
CLIENT:	CONDEA Spa
LOCATION/PROJECT:	Petrochemical, Augusta Sicily Island, (ITALY)
DESCRIPTION OF WORK:	General Assistance for the construction of the Oil Peer.
YEAR:	2002
CLIENT:	COMUNE DI PROCIDA
LOCATION/PROJECT:	ITALY, ON-SHORE PROCIDA
DESCRIPTION OF WORK:	Supply of services and related works finalized to the experimentation of a new Beach Management System (BMS™) technology for the restoration of the beach by draining of the water's edge.
YEAR:	2002
CLIENT:	NAOC / AENR
LOCATION/PROJECT:	OML – 119 Okono Field,(NIGERIA)
DESCRIPTION OF WORK:	Saturation Diving Assistance for Christmas tree Installation at Okono 2 & 3 (Saturation System)
YEAR:	2002
CLIENT:	CONSORZIO VENEZIA NUOVA
LOCATION/PROJECT:	ITALY, Venice Lagoon Italy
DESCRIPTION OF WORK:	Bathymetric survey: very high-resolution bathymetric survey using Multi-beam technique to update the Lagoon Data Base and the official Charts – VENICE NORD

YEAR:	2001
CLIENT:	PETROBEL
LOCATION/PROJECT:	(EGYPT)
DESCRIPTION OF WORK:	North Port Said Concession – Mediterranean Sea – Mediterranean Offshore survey – New Route Survey Pron RPP to Shore
YEAR:	2001
CLIENT:	NAOC
LOCATION/PROJECT:	kwale Flow station (NIGERIA)
DESCRIPTION OF WORK:	14" Pipeline Repair with Plidco Clamp Installation
YEAR:	2001
CLIENT:	CONDEA Spa
LOCATION/PROJECT:	Petrochemical, Augusta Sicily Island, (ITALY)
DESCRIPTION OF WORK:	Project of Oil peer Construction, Preliminary Dredging included.
YEAR:	2001
CLIENT:	DRAGON OIL CO.
LOCATION/PROJECT:	(TURKMENISTAN)
DESCRIPTION OF WORK:	Diving services for 12"/18" Tie-in and spools installation – Caspian Sea
YEAR:	2001
CLIENT:	SIOT Spa
LOCATION/PROJECT:	Trieste – (ITALY)
DESCRIPTION OF WORK:	Water intake restoration.
YEAR:	2001
CLIENT:	AGIP PETROLI Spa
LOCATION/PROJECT:	Milazzo Sicily Island – (ITALY)
DESCRIPTION OF WORK:	Complete restoration of oil peers and piles, Revamping of Cathodic protection, splash zone coating. Underwater survey and NDT Inspection
YEAR:	2001
CLIENT:	NAOC /AENR
LOCATION/PROJECT:	OML – 119 Okono Field,(NIGERIA)
DESCRIPTION OF WORK:	Diving Services during Drilling Operations at Okono 4 & 5 Well Heads
YEAR:	2001
CLIENT:	NAOC
LOCATION/PROJECT:	Kwale Flow station, (NIGERIA)
DESCRIPTION OF WORK:	14" Pipeline Repair with Plidco Clamp Installation
YEAR:	2001
CLIENT:	CONDEA Spa
LOCATION/PROJECT:	Petrochemical, Augusta Sicily Island, (ITALY)
DESCRIPTION OF WORK:	Project of Oil peer Construction, Preliminary Dredging included.
YEAR:	2001
CLIENT:	DRAGON OIL CO.
LOCATION/PROJECT:	(TURKMENISTAN)
DESCRIPTION OF WORK:	Diving services – Laying & installation of 12" Caspian Sea.

YEAR: 2001
CLIENT: PETROBEL
LOCATION/PROJECT: (EGYPT)
DESCRIPTION OF WORK: North Port Said Concession – Post Trenching for 12” + 3” Sealines from Port Fouad M-SW2 to Port Fouad Platform As-Laid Survey

YEAR: 2001
CLIENT: PETROBEL
LOCATION/PROJECT: (EGYPT)
DESCRIPTION OF WORK: Temsah Development Project – Post Trenching for sealines 12”+4”+3” and 32”+12”+4”+3” sealine from Temsah NW1/3 platform to shore – as built survey.

YEAR: 2001
CLIENT: TERNA
LOCATION/PROJECT: (ITALY)
DESCRIPTION OF WORK: Tirrenian Sea – Underwater Inspections and maintenance (repair) of the SA.CO.I power cables: this includes 5 shore approach areas located in Italy main land, Sardinia and Corsica Islands. The job was performed by using divers equipped with sub-inspection instruments.

YEAR: 2001
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Field (NIGERIA)
DESCRIPTION OF WORK: Close Visual Inspection, Non Destructive test on Buoy Operating Platform.

YEAR: 2000
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Terminal, Bayelsa State (NIGERIA)
DESCRIPTION OF WORK: Diving Services and Offshore Maintenance of Buoy Operating Platform, No 2 SPM, and Pipelines.

YEAR: 2000
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Terminal (NIGERIA)
DESCRIPTION OF WORK: 32” & 36” pipeline Inspection (NDT) and Repair of damaged area (including No. 6 joints) with sub Epoxy coat.Partial Revamping of cathodic protection (Installation of some new anodes) – Saturation System

YEAR: 2000
CLIENT: ESSO
LOCATION/PROJECT: Augusta Sicily Island (ITALY)
DESCRIPTION OF WORK: Complete Restoration of all the damaged parts of the oil pear.

YEAR: 2000
CLIENT: I.E.O.C
LOCATION/PROJECT: (EGYPT)
DESCRIPTION OF WORK: Mediterranean Sea – East Delta Deep Marine Concession – Two Deep Water Well Site Surveys on Haret and Talaab locations: 8 X 8 km Analog: bathymorphological and very high resolution geophysical prospecting, magnetometer survey and coring for on-board description and laboratory geotechnical analysis.

2 x 2 km Digital: multichannel high resolution seismic survey. Post processing and interpretation of the data up to identify seabed and buried hazards.

YEAR: 2000
CLIENT: NAOC
LOCATION/PROJECT: Benibioye Oil Field (NIGERIA)
DESCRIPTION OF WORK: Repair of No 3 pipelines Ø 8"/10"/12", excavation and Plidco Clamp Installation on the damaged sides.

YEAR: 2000
CLIENT: REGIONE LAZIO
LOCATION/PROJECT: (ITALY)
DESCRIPTION OF WORK: Supply of services and related works finalized to the experimentation of a new Beach Management System (BMS™) technology for the restoration of the beach by draining of the water's edge.

YEAR: 1999
CLIENT: AENR
LOCATION/PROJECT: Agbara Oil Field
DESCRIPTION OF WORK: Riser and Spool piece Installation (16")

YEAR: 1999
CLIENT: ISMES Spa
LOCATION/PROJECT: Civitavecchia Offshore (ITALY)
DESCRIPTION OF WORK: Underwater test assistance, fitting up instruments for measuring waves and current action, installation of special supports on the Sea bottom

YEAR: 1999
CLIENT: AGIP PETROLI Spa
LOCATION/PROJECT: Coastal Terminal (ITALY)
DESCRIPTION OF WORK: Refurbishing of monitors and fire proof Systems

YEAR: 1999
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Terminal, Bayelsa State (NIGERIA)
DESCRIPTION OF WORK: Diving Services for SPM Change Out with Support Vessel Dynamic Installer (SBM)

YEAR: 1999
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Terminal, Bayelsa State (NIGERIA)
DESCRIPTION OF WORK: Diving Services and Offshore Maintenance of Buoy Operating Platform, No 2 SPM, and 36" Pipelines (ROV Inspection).

YEAR: 1999
CLIENT: ESSO Spa
LOCATION/PROJECT: Refinery of Augusta Sicily Island –(ITALY)
DESCRIPTION OF WORK: Structural restoration of oil peer splash zone coating concrete casting included.

YEAR:	1999
CLIENT:	PETROBEL
LOCATION/PROJECT:	(EGYPT)
DESCRIPTION OF WORK:	Karous 1 Development Projects –Sealines Trenching: 30” and 12” using a dedicated P.T.M Post Trenching Machine for a total length of 8 km. The contract includes the Route Clearing, Post trenching survey using R.O.V equipped with pipe-tracker and dual head sonar.
YEAR:	1999
CLIENT:	ADRIATIC SUB AGIP
LOCATION/PROJECT:	Adriatic Sea (ITALY)
DESCRIPTION OF WORK:	Jolel Project – pipeline route survey, along the corridor linking the sealine “Davide to Shore” with the new Jolel Monopile Platform: bathymorphological and very high resolution geophysical prospecting, in order to define the seabed features, the morphological parameters of the laying route, slopes and total length on sea bed.
YEAR:	1999
CLIENT:	AGIP ENERGY
LOCATION/PROJECT:	Agbara Oil Field (NIGERIA)
DESCRIPTION OF WORK:	Flare Tower and gas flow line survey; including CVI Inspection of the Buoy Hull.
YEAR:	1999
CLIENT:	COGEI Spa
LOCATION/PROJECT:	Republic of Capoverde Islands.
DESCRIPTION OF WORK:	Trenching, Launching and Burring of 24” sewage out-fall pipeline (1,200 km)
YEAR:	1999
CLIENT:	ELETTRA/TELECOM
LOCATION/PROJECT:	(ITALY)
DESCRIPTION OF WORK:	Sicily Strait – Shore approach route survey: Geomorphological and very high resolution marine sampling, diving inspection and land topographic survey in the shore-end areas of Pelagie Island: Lampedusa – Licata – Pantelleria – Mazara for the new fibre optic telecommunication cable links. Scope of work includes the route studying and the burial feasibility analysis.
YEAR:	1999
CLIENT:	PIRELLI CAVI
LOCATION/PROJECT:	(ITALY)
DESCRIPTION OF WORK:	Malta Channel – Diving Services for Cable Repairing.
YEAR:	1998
CLIENT:	PORT AUTHORITY
LOCATION/PROJECT:	Finale Ligure, Tirreno Sea (ITALY)
DESCRIPTION OF WORK:	Project, fabrication, supply, laying and backfilling of 1,600m. Pipeline
YEAR:	1998
CLIENT:	MINISTRY OF PUBLIC WORKS
LOCATION/PROJECT:	Port of Talamone – (ITALY)
DESCRIPTION OF WORK:	Port quay walls repair.

YEAR: 1998
CLIENT: PORT AUTHORITY
LOCATION/PROJECT: Port of Augusta – Sicily – (ITALY)
DESCRIPTION OF WORK: General and close visual inspection of the structures; daily and final report and technical proposal for repair works.

YEAR: 1998
CLIENT: AGIP PETROLI Spa
LOCATION/PROJECT: ViboValentia, Oil Terminal (ITALY)
DESCRIPTION OF WORK: Repair of two 12" Oil Pipelines by Tie-Ins

YEAR: 1998
CLIENT: NAOC
LOCATION/PROJECT: Brass Oil Terminal (NIGERIA)
DESCRIPTION OF WORK: ROV's General Visual Inspection of the 32" and 36" export pipelines.

YEAR: 1998
CLIENT: AGIP ENERGY
LOCATION/PROJECT: Agbara Oil Field (NIGERIA)
DESCRIPTION OF WORK: Flare Tower and gas flow line inspection. CVI & NDT Inspection on Production Platform